

ms65

From: WASHINGTON

To: MOSCOW

No.: 1514

4 July 1943

According to a report by KLADOV the following cases of sabotage took place during repair of the "VANTsETTI" at the East Coast Shipyard in New York:

1. Two cases of small fires on 7 April and 10 April where electric welding was taking place.
2. On 14 June during tests of the dynamo it was discovered that sand had been sprinkled in the crankcase oil.
3. On 15 June, in a centrifugal pump which was undergoing major overhaul by the factory, the packing was deliberately installed in such a way that the oil could not get to the bearings, causing the shaft to overheat in the test.
4. On 15 June [2 groups unrecovered] for testing the heavy boom, the TOPTIK(a) lying on the upper deck [4 groups unrecovered] in two places and was unfit for further work.
5. On 11 June [4 groups unrecovered] padlock.
[132 groups unrecovered and unrecoverable]

(a) Meaning unknown.

BRIDE